

- 1. Reinforcement not shown for clarity
- 2. Fix truss to top plate with approved mechanical fix
- 3. Refer clause E2/AS3 of the NZ Building Code for full weathertightness detailing of the roof structure and eaves

