


Note: Reinforcement not shown for clarity.

Internal Gutter Detail



For alternative details refer to CCANZ CP 01:2011 code of practice for weathertight concrete and concrete masonry construction.

Flashing Detail